







1. EXPORT TO DWG.




2. CLICK ADDITIONAL SETTINGS (THREE DOTS).




3. SET COLOUR TO "SPECIFIED IN VIEW".



4. SET SOLIDS TO "ACIS SOLIDS".



5. SET UNITS TO MILLIMETERS.



6. CLICK OK TO GET TO SAVE MENU. UNCHECK "EXPORT VIEWS ... AS EXTERNAL REFERENCES". THIS KEEPS EVERYTHING IN ONE DWG FILE.